Team Air Conditioning

Team Air Conditioning, Inc. 16520 South Tamiami Trail Suite 207 Fort Myers, FL 33908



,							
Repair Number De	escription	Standard Rate	Additional Rate	Overtime Rate	Overtime Additional	Esa Rate	Esa Additional
MOT-BLW	Replace Blower Motor						
		\$560.71	\$477.66	\$642.77	\$615.42	\$505.35	\$488.94
BLW010000 - 060		115V 3 Spee	d Blower Moto	or			
			As a	maintenance	agreement cus	stomer, you sa	ve: \$55.35
Capacitor Included							
		\$570.58	\$486.04	\$652.65	\$625.29	\$514.23	\$497.82
BLW010005 - 060	Replace 1/4 HP 1075 RPM	230V 3 Spee			areement cur	stomer, you sa	ve: \$56.35
Capacitor Included			AS d	maintenance	agreement cut	storrer, you sa	ve. \$50.55
		\$570.58	\$486.04	\$652.65	\$625.29	\$514.23	\$497.82
BLW010010 - 060		-	•				,
As a maintenance agreement customer, you save: \$56.35							
Capacitor Included							
		\$580.63	\$494.58	\$662.69	\$635.34	\$523.26	\$506.85
BLW010015 - 060	Replace 1/3 HP 1075 RPM	230V 3 Spee					• • -
Conceitor Included			As a	maintenance	agreement cus	stomer, you sa	ve: \$57.37
Capacitor Included		\$589.10	\$501.79	\$671.17	\$643.82	\$530.91	\$514.49
BLW010020 - 060		-		-	\$043.0 2	\$530.91	\$514.49
					agreement cus	stomer, you sa	ve: \$58.19
Capacitor Included							
		\$597.84	\$509.23	\$679.90	\$652.55	\$538.77	\$522.36
BLW010025 - 060	Replace 1/2 HP 1075 RPM	230V 3 Spee	d Blower Moto	or			
			As a	maintenance	agreement cus	stomer, you sa	ve: \$59.07
Capacitor Included							
		\$1,244.88	\$1,059.21	\$1,345.88	\$1,312.22	\$1,121.09	\$1,100.89
BLW010030 - 075	5 Replace 1/2 HP Variable S	peed Blower I		maintenance	agreement cus	stomer, you sa	ve [.] \$123 79
With Built-In Control	Module		, io u				
		\$1,426.87	\$1,213.89	\$1,527.87	\$1,494.20	\$1,284.89	\$1,264.69
BLW010035 - 075			-	÷.,521101	¥ 1,101120	Ţ., 20 7100	÷.,207.00
				maintenance	agreement cus	stomer, you sa	ve: \$141.98
With Built-In Control							
		\$480.90	\$409.84	\$525.09	\$510.37	\$433.53	\$424.69
BLW010040 - 030) Replace 1/2 HP Variable S	peed Motor M		maintonana	aroom and and	tomor	NO: 047 07
Capacitor Included			As a	maintenance	agreement cus	stomer, you sa	ve: \$47.37

Team Air Conditioning

Team Air Conditioning, Inc. 16520 South Tamiami Trail Suite 207 Fort Myers, FL 33908



Repair Number Des	cription	Standard Rate	Additional Rate	Overtime Rate	Overtime Additional	Esa Rate	Esa Additional
		\$480.90	\$409.84	\$525.09	\$510.37	\$433.53	\$424.69
BLW010045 - 030	Replace 3/4 HP Variable S	-	-	\$020.00	<i>Q</i> 010.0 <i>1</i>	¥-100.00	ψ-12-1.00
BEHICIOCIO 000				aintenance a	greement cus	tomer, you sa	ive: \$47.37
Capacitor Included					•		
MOT-CON	Replace Condenser Fa	n Motor					
	Replace Condensel Fa						
		\$421.95	\$358.95	\$504.02	\$476.67	\$379.95	\$363.54
CON010000 - 060	Replace 1/6 HP 825 RPM	230V Condense	er Fan Motor				
			As a m	aintenance a	greement cus	tomer, you sa	ve: \$42.00
Capacitor Included							
		\$432.28	\$367.74	\$514.34	\$486.99	\$389.25	\$372.84
CON010005 - 060	Replace 1/4 HP 825 RPM	230V Condense	er Fan Motor				
			As a m	naintenance a	greement cus	tomer, you sa	ive: \$43.03
Capacitor Included							
		\$443.46	\$377.24	\$525.53	\$498.17	\$399.32	\$382.91
CON010010 - 060	Replace 1/3 HP 825 RPM		-	<i>v</i> uuuu	V 100111	+••••=	<i>v</i> vvu
				aintenance a	greement cus	tomer vou sa	we [.] \$44.14
Capacitor Included			710 4 11			tonner, you oc	φιι
		* ****	A044 70	A 454 07	* 40.4.00	****	AA4A 74
		\$369.91	\$314.72	\$451.97	\$424.62	\$333.12	\$316.71
CON010015 - 060	Replace 1/4 HP 1075 RPM	1230V Condens					*••••
			As a m	aintenance a	igreement cus	tomer, you sa	ive: \$36.79
Capacitor Included							
		\$378.49	\$322.02	\$460.55	\$433.20	\$340.85	\$324.44
CON010020 - 060	Replace 1/3 HP 1075 RPI	M 230V Condens					
			As a m	naintenance a	igreement cus	tomer, you sa	ive: \$37.64
Capacitor Included							
		\$381.58	\$324.65	\$463.64	\$436.29	\$343.64	\$327.23
CON010025 - 060	Replace 1/2 HP 1075 RPI	VI 230V Condens	ser Fan Motor	-			
			As a m	aintenance a	greement cus	tomer, you sa	ive: \$37.94
Capacitor Included							
		\$427.75	\$363.87	\$509.81	\$482.46	\$385.16	\$368.75
CON010030 - 060	Replace 3/4 HP 1075 RPI	V 230V Condens	ser Fan Motor				·
					greement cus	tomer, vou sa	ve: \$42.59
Capacitor Included					-		
		\$536.06	\$455.94	\$618.12	\$590.77	\$482.66	\$466.24
CON010035 - 060	Replace 1/4 HP 1075 RPI	-	•			ψτ02.00	Ψ 1 00.24
0010010035-000	Replace 14 HE 10/3 REI	vi 200 vi lotaliy E				tomer vou co	WA: \$52.40
Conscitor Induded			Asam	annenance a	igreement cus	tomer, you sa	IVE. 000.40
Capacitor Included							

Team Air Conditioning

Team Air Conditioning, Inc. 16520 South Tamiami Trail Suite 207 Fort Myers, FL 33908



Repair Number Description	Standard Rate	Additional Rate	Overtime Rate	Overtime Additional	Esa Rate	Esa Additional		
	\$565.50	\$480.98	\$647.57	\$620.21	\$509.16	\$492.75		
CON010040 - 060 Replace 1/3 HP 1075 RPM	I 230V Totally	Enclosed Con	denser Fan M	lotor				
		As a n	naintenance a	agreement cust	tomer, you sa	ve: \$56.34		
Capacitor Included								
	\$551.57	\$469.13	\$633.64	\$606.29	\$496.61	\$480.20		
CON010045 - 060 Replace 1/2 HP 1075 RPM	I 230V Totally	Enclosed Con	denser Fan M	lotor				
		As a n	naintenance a	agreement cust	tomer, you sa	ve: \$54.96		
	\$684.35	\$581.99	\$766.42	\$739.06	\$616.12	\$599.71		
CON010050 - 060 Replace 3/4 HP 1075 RPM	0 Replace 3/4 HP 1075 RPM 230V Totally Enclosed Condenser Fan Motor							
		As a n	naintenance a	agreement cust	tomer, you sa	ve: \$68.23		
Capacitor Included								
	\$674.92	\$573.98	\$756.98	\$729.63	\$607.62	\$591.21		
CON010055 - 060 Replace 1/4 HP 1075 Rpm	230V O.E.M.	Condenser Mo	otor					
		As a n	naintenance a	agreement cust	tomer, you sa	ve: \$67.30		
Capacitor Included								
	\$774.17	\$658.35	\$856.24	\$828.89	\$696.96	\$680.55		
CON010060 - 060 Replace 1/3 HP 1075 RPM	Replace 1/3 HP 1075 RPM 230V O.E.M. Condenser Motor							
		As a n	naintenance a	agreement cust	tomer, you sa	ve: \$77.21		
Capacitor Included								
	\$201.29	\$171.39	\$283.35	\$256.00	\$181.36	\$164.94		
CON010065 - 060 Replace Condenser Fan Mo	otor Under Wa	rranty						
		As a n	naintenance a	agreement cust	tomer, you sa	ve: \$19.93		
Capacitor Included								
	\$130.31	\$111.08	\$174.50	\$159.78	\$117.48	\$108.64		
CON010070 - 030 Replace Motor Rain Shield								
	As a maintenance agreement customer, you save: \$12.83							
	\$67.19	\$57.42	\$79.81	\$75.60	\$60.67	\$58.14		
CON010075 - 005 Replace Motor Rain Shield	with Motor Re	placement						
		As a n	naintenance a	agreement cust	tomer, you sa	ve: \$6.52		