

# Spiff Report

Team Air Conditioning, Inc.  
16520 South Tamiami Trail  
Suite 207  
Fort Myers, FL 33908



SubGroup	Repair Number	Description	Spiff Amount
<b>AVL</b>	<b>Access Valves</b>		
	AVL010000	Replace 1/4" Flare Swivel Access Tee	\$1.25
	AVL010005	Install Up to 5/8" Line Tap Valve	\$1.25
	AVL010010	Install Up to 3/8" Saddle Valve	\$1.25
	AVL010015	Replace Schrader Valve Cap	\$1.25
	AVL010020	Replace Schrader Valve Core	\$1.25
<b>BLT</b>	<b>Belt</b>		
	BLT110000	Replace 3L Type V-Belt Up to 36"	\$1.00
	BLT110005	Replace 3L Type V-Belt Up to 36" with Other Repair	\$1.00
	BLT110010	Replace 4L Type V-Belt Up to 36"	\$1.00
	BLT110015	Replace 4L Type V-Belt Up to 36" with Other Repair	\$1.00
	BLT110020	Replace 3L Type V-Belt Up to 48"	\$1.00
	BLT110025	Replace 3L Type V-Belt Up to 48" with Other Repair	\$1.00
	BLT110030	Replace 4L Type V-Belt Up to 48"	\$1.00
	BLT110035	Replace 4L Type V-Belt Up to 48" with Other Repair	\$1.00
<b>BLW</b>	<b>Blower</b>		
	BLW010000	Replace 1/4 HP 1075 RPM 115V 3 Speed Blower Motor	\$5.00
	BLW010005	Replace 1/4 HP 1075 RPM 230V 3 Speed Blower Motor	\$5.00
	BLW010010	Replace 1/3 HP 1075 RPM 115V 3 Speed Blower Motor	\$5.00
	BLW010015	Replace 1/3 HP 1075 RPM 230V 3 Speed Blower Motor	\$5.00
	BLW010020	Replace 1/2 HP 1075 RPM 115V 3 Speed Blower Motor	\$5.00
	BLW010025	Replace 1/2 HP 1075 RPM 230V 3 Speed Blower Motor	\$5.00
	BLW010030	Replace 1/2 HP Variable Speed Blower Motor	\$5.00
	BLW010035	Replace 3/4 HP Variable Speed Blower Motor	\$5.00
	BLW010040	Replace 1/2 HP Variable Speed Motor Module	\$5.00
	BLW010045	Replace 3/4 HP Variable Speed Motor Module	\$5.00
<b>BRK</b>	<b>Breaker</b>		
	BRK110000	Replace 2 Pole 30 Amp Plug-In Circuit Breaker	\$2.25
	BRK110005	Replace 2 Pole 40 Amp Plug-In Circuit Breaker	\$2.25
	BRK110010	Replace 2 Pole 50 Amp Plug-In Circuit Breaker	\$2.25
	BRK110015	Replace 2 Pole 60 Amp Plug-In Circuit Breaker	\$2.25