

Team Air Conditioning

Team Air Conditioning, Inc.
 16520 South Tamiami Trail
 Suite 207
 Fort Myers, FL 33908













Repair Number	Description	Standard Rate	Overtime Rate	Value Rate	Value Savings
MOT-BLW	Replace Blower Motor				
		\$560.71	\$642.77	\$505.35	\$55.36
BLW010000 - 060	Replace 1/4 HP 1075 RPM 115V 3 Speed Blower Motor				As a value customer, you save: \$55.36
Capacitor Included					
		\$570.58	\$652.65	\$514.23	\$56.35
BLW010005 - 060	Replace 1/4 HP 1075 RPM 230V 3 Speed Blower Motor				As a value customer, you save: \$56.35
Capacitor Included					
		\$570.58	\$652.65	\$514.23	\$56.35
BLW010010 - 060	Replace 1/3 HP 1075 RPM 115V 3 Speed Blower Motor				As a value customer, you save: \$56.35
Capacitor Included					
		\$580.63	\$662.69	\$523.26	\$57.37
BLW010015 - 060	Replace 1/3 HP 1075 RPM 230V 3 Speed Blower Motor				As a value customer, you save: \$57.37
Capacitor Included					
		\$589.10	\$671.17	\$530.91	\$58.19
BLW010020 - 060	Replace 1/2 HP 1075 RPM 115V 3 Speed Blower Motor				As a value customer, you save: \$58.19
Capacitor Included					
		\$597.84	\$679.90	\$538.77	\$59.07
BLW010025 - 060	Replace 1/2 HP 1075 RPM 230V 3 Speed Blower Motor				As a value customer, you save: \$59.07
Capacitor Included					
		\$1,244.88	\$1,345.88	\$1,121.09	\$123.79
BLW010030 - 075	Replace 1/2 HP Variable Speed Blower Motor				As a value customer, you save: \$123.79
With Built-In Control Module					
		\$1,426.87	\$1,527.87	\$1,284.89	\$141.98
BLW010035 - 075	Replace 3/4 HP Variable Speed Blower Motor				As a value customer, you save: \$141.98
With Built-In Control Module					
		\$480.90	\$525.09	\$433.53	\$47.37
BLW010040 - 030	Replace 1/2 HP Variable Speed Motor Module				As a value customer, you save: \$47.37
Capacitor Included					

Team Air Conditioning

Team Air Conditioning, Inc.
 16520 South Tamiami Trail
 Suite 207
 Fort Myers, FL 33908









Repair Number	Description	Standard Rate	Overtime Rate	Value Rate	Value Savings
		\$480.90	\$525.09	\$433.53	\$47.37
BLW010045 - 030	Replace 3/4 HP Variable Speed Motor Module				
As a value customer, you save: \$47.37					
Capacitor Included					
MOT-CON	Replace Condenser Fan Motor				
		\$421.95	\$504.02	\$379.95	\$42.00
CON010000 - 060	Replace 1/6 HP 825 RPM 230V Condenser Fan Motor				
As a value customer, you save: \$42.00					
Capacitor Included					
		\$432.28	\$514.34	\$389.25	\$43.03
CON010005 - 060	Replace 1/4 HP 825 RPM 230V Condenser Fan Motor				
As a value customer, you save: \$43.03					
Capacitor Included					
		\$443.46	\$525.53	\$399.32	\$44.14
CON010010 - 060	Replace 1/3 HP 825 RPM 230V Condenser Fan Motor				
As a value customer, you save: \$44.14					
Capacitor Included					
		\$369.91	\$451.97	\$333.12	\$36.79
CON010015 - 060	Replace 1/4 HP 1075 RPM 230V Condenser Fan Motor				
As a value customer, you save: \$36.79					
Capacitor Included					
		\$378.49	\$460.55	\$340.85	\$37.64
CON010020 - 060	Replace 1/3 HP 1075 RPM 230V Condenser Fan Motor				
As a value customer, you save: \$37.64					
Capacitor Included					
		\$381.58	\$463.64	\$343.64	\$37.94
CON010025 - 060	Replace 1/2 HP 1075 RPM 230V Condenser Fan Motor				
As a value customer, you save: \$37.94					
Capacitor Included					
		\$427.75	\$509.81	\$385.16	\$42.59
CON010030 - 060	Replace 3/4 HP 1075 RPM 230V Condenser Fan Motor				
As a value customer, you save: \$42.59					
Capacitor Included					
		\$536.06	\$618.12	\$482.66	\$53.40
CON010035 - 060	Replace 1/4 HP 1075 RPM 230V Totally Enclosed Condenser Fan Motor				
As a value customer, you save: \$53.40					
Capacitor Included					

Team Air Conditioning

Team Air Conditioning, Inc.
 16520 South Tamiami Trail
 Suite 207
 Fort Myers, FL 33908



Repair Number	Description	Standard Rate	Overtime Rate	Value Rate	Value Savings
		\$565.50	\$647.57	\$509.16	\$56.34
CON010040 - 060	Replace 1/3 HP 1075 RPM 230V Totally Enclosed Condenser Fan Motor				
	As a value customer, you save:				\$56.34
Capacitor Included					
		\$551.57	\$633.64	\$496.61	\$54.96
CON010045 - 060	Replace 1/2 HP 1075 RPM 230V Totally Enclosed Condenser Fan Motor				
	As a value customer, you save:				\$54.96
		\$684.35	\$766.42	\$616.12	\$68.23
CON010050 - 060	Replace 3/4 HP 1075 RPM 230V Totally Enclosed Condenser Fan Motor				
	As a value customer, you save:				\$68.23
Capacitor Included					
		\$674.92	\$756.98	\$607.62	\$67.30
CON010055 - 060	Replace 1/4 HP 1075 Rpm 230V O.E.M. Condenser Motor				
	As a value customer, you save:				\$67.30
Capacitor Included					
		\$774.17	\$856.24	\$696.96	\$77.21
CON010060 - 060	Replace 1/3 HP 1075 RPM 230V O.E.M. Condenser Motor				
	As a value customer, you save:				\$77.21
Capacitor Included					
		\$201.29	\$283.35	\$181.36	\$19.93
CON010065 - 060	Replace Condenser Fan Motor Under Warranty				
	As a value customer, you save:				\$19.93
Capacitor Included					
		\$130.31	\$174.50	\$117.48	\$12.83
CON010070 - 030	Replace Motor Rain Shield				
	As a value customer, you save:				\$12.83
		\$67.19	\$79.81	\$60.67	\$6.52
CON010075 - 005	Replace Motor Rain Shield with Motor Replacement				
	As a value customer, you save:				\$6.52